

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2073	Date	8th August, 2014
Manufacture	Caterpillar Japan LTD		
Description of Deffect	Due to the invasion of soil and so on, spline of front axle shaft may be worn out. This causes unappropriate power transmission and/or parking brake force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN-JRS	「907H2」	2013 - 2014	81
		TOTAL	81