## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

		D	omestic Import Vehicles
CAMPAIGN No.	GAI-2043	DATE	August 14, 2014
MANUFACTURE	Indian Motorcycle Company		
	(Japanese Importer : V	Vhite House Co. Ltd.	)
DESCRIPTION OF DEFECT	The rear rim used on affected vehicles may have the less cross-sectional thickness that does not meet specification because of the improper manufacturing. Therefore, the rim may crack and cause a loss of air pressure while riding. This could cause the vehicle operator to lose control and stability.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5YAC 5VP1	Chief Vintage		25
	Chief Classic		15
	Chief Dark Horse	2008~2012	11
	Chief Blackhawk		7
	Chief Roadmaster		7
	Chief Deluxe		
			3
		TOTAL	68