

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI – 2052	DATE	Aug 22, 2014
MANUFACTURE	LOTUS CARS Plc (Japanese Importer :LCI Limited )		
DESCRIPTION OF DEFECT	Engine oil cooler hose design inappropriate resulting, in some cases, in coupler becoming loose and loss of engine oil. In a worst case scenario this can lead to engine failure and/or fire.		

TYPE	COMMERCAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-122	「EVORA S」	2011MY	12
-122-	「EVORA S」	2011MY	8
GH-1117	「ELISE R」	2005MY～2007MY	269
ABA-1117	「ELISE R」	2007MY～2011MY	171
	「ELISE SC」	2008MY～2011MY	111
-1117-	「ELISE SC」	2008MY	12
GH-1117	「EXIGE」	2004MY～2007MY	266
ABA-1117	「EXIGE」	2007MY～2008MY	25
GH-1117	「EXIGE S」	2006MY～2007MY	120
ABA-1117	「EXIGE S」	2007MY～2011MY	148
-1117-	「EXIGE S」	2008MY	7
	「EXIGE CUP190」	2006MY	10
	「EXIGE CUP240」	2005MY～2007MY	33
	「EXIGE CUP255」	2007MY	2
	「EXIGE CUP260」	2009MY～2011MY	34
	「EXIGE STELTH」	2010MY	5

	「EXIGE ClubRacer」	2011MY	18
	「EXIGE 240R」	2005MY	10
UNKNOWN	「2-Eleven」	2007MY～2009MY	65
		TOTAL	1326