

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 4 2 9	DATE	Aug 26,2014
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	<p>Inappropriate wheel disk paint thickness and inappropriate wheel nut tightening at time of manufacturing have been identified on travel devices of wheel cranes.</p> <p>Therefore, with continued use in these conditions, there is a risk of the nut is loosening with travel related vibrations.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-T008	TADANO 「GR-700N-1」	2014	51
UDS-T007	TADANO 「GR-250N-3」	2014	93
UDS-T009	TADANO 「GR-160N-3」	2013-2014	96
UDS-EW07	KOBELCO 「RK160-7」	2014	19
		<b>TOTAL</b>	<b>259</b>