

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2079	DATE	August 28, 2014
MANUFACTURE	KR Motors Co., Ltd. (Japanese Importer : Japan Auto Press Co., Ltd.)		
DESCRIPTION OF DEFECT	Some drive chains have defect that strength of pins are poor by reason of failure in production control. When the chain has been used, the pin is broken and the link was cut, then driving power is not transferred to the rear wheel. In the worst case, the vehicle falls down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GV250	GV250	2012	240
		TOTAL	240