

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2084	DATE	Aug. 20, 2014
MANUFACTURER	TADANO LTD.		
DESCRIPTION OF DEFECT	Low-pressure hose deterioration progresses when the hydraulic oil filter element is dirt, and a warning light turned on and the low pressure hose which passed the replacement period in the oil pressure circuits such as steering arrangements. Therefore when continue using it, the low-pressure hose cracks, and hydraulic oil flows out and might disturb security of other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	RTF360G-6	2009-2012	29
-	ATF60J-3	2009-2011	10
TOTAL			39