

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic

Campaign No.	3438	Date	30,September, 2014
Manufacturer	Kobelco Construction Machinery Co., Ltd.		
Description of Defect	<p>Regarding electric wires routed under the operator's seat, the fixed positions of electric wires are not appropriate. This cause a steering system to interfere with electric wires, when an operator pulls the steering system toward him/her for adjusting its angle. If this type of machines is continued to use "as is" without any improvements or rectifications, electric wires will be damaged and broken due to vibration of the machine. In the worst case, a fuse will blow out and a parking brake will not be released. Headlamps, position lamps and turn-signal lamps will also do not work.</p>		

Type	Commercial Name	Model year recalled	Number of Vehicles
EDR-YE04	「SK125W」	2012～2013	40
Total			40