

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2086	DATE	Sep 18, 2014
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd. )		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in all 2010-2014 model year Chevrolet Camaro vehicles. There is a risk, under certain conditions, that some drivers may bump the ignition key with their knee and unintentionally move the key away from the “run” position. If this occurs, engine power, and power braking will be affected and power steering may be affected, increasing the risk of a crash. The timing of the key movement out of the “run” position, relative to the activation of the sensing algorithm of the crash event, may result in the airbags not deploying, increasing the potential for occupant injury in certain kinds of crashes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
—	「CAMARO」	2010 - 2014	872
		TOTAL	872