

VEHICLE SAFETY／POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	3425	DATE	12 September 2014
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO. , LTD		
DESCRIPTION OF DEFECT	In the rotary snow removers which are equipped heated front window, because of the electric current capacity for the electric connector is short. If it is used continuously, the worst there is possibility the electric connector will burn.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
M05	「JR180」	1998 - 2002	53
RH400	「JR300」	2001	1
JR300		1998 - 2000	14
M06		2000 - 2001	22
R600	「JR440」	1999	2
JR440		2001	2
		TOTAL	94