

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3428	DATE	Sep. 11, 2014
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to improper programming on ECU (Engine Control Unit), catalyst deterioration diagnosis may not be performed properly. Therefore, warning lamp may not illuminate when catalyst deteriorates.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2014	6,382
DBA-VMG		2014	1,964
		TOTAL	8,346