

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3431	DATE	Sep.10.2014
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>On the fuel system of the subject vehicles equipped with a diesel engine, due to insufficient strength of the fuel filter installed on the engine, if the engine is frequently started and stopped, a crack could develop in the fuel filter housing by changes of the fuel pressure. If the vehicle is continuously operated in this condition, the crack could expand causing the fuel filter case to become damaged and in the worst case, fuel could leak from the fuel filter.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-XZU282K TKG-XZU282K	QUICK DELIVERY	2012-2013	204
TOTAL			204