

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2080	DATE	September 5 th 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>It cannot be ruled out that, due to long-term influences in areas with a high level of air humidity, moisture gets into the housing of the gas generator on the front-side front passenger airbag caused by possibility of an inflator manufacturing error.</p> <p>In this case, if the front passenger airbag is activated, there may be an increased volume of internal pressure.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-AT18	BMW 316ti	2001 – 2004	2,244
GF-AL19	BMW 318i	1999 – 2000	4,558
	BMW 318i Touring	1999 – 2000	1,831
	BMW 318Ci	1999 – 2000	1,290
GH-AL19	BMW 318i	2000 – 2001	8,170
	BMW 318i Touring	2000 – 2001	2,346
	BMW 318Ci	2000 – 2001	1,032
GH-AY20	BMW 318i	2001 – 2005	17,051
	BMW 318i Touring	2001 – 2005	7,635
	BMW 318Ci	2001 – 2005	1,936
GH-BX20	BMW 318Ci	2005 – 2006	481
GH-AU20	BMW 318ti	2001 – 2004	3,305
GF-AM20	BMW 320i	1999 – 2000	5,180
GH-AV22		2000 – 2004	22,250
GF-AM25	BMW 323i	1999 – 2000	1,824
GH-AV25	BMW 325i	2000 – 2004	4,456
	BMW 325i Touring	2000 – 2005	2,625
GF-AM28	BMW 328i	1999 – 2000	863
	BMW 328Ci	1999 – 2000	712
GH-AV30	BMW 330i	2000 – 2004	3,653
	BMW 330Xi	2001 – 2004	136
	BMW 330Ci	2000 – 2006	2,050
	BMW 330Ci Cabriolet	2000 – 2006	1,871

GF-BL32	BMW M3	2001 – 2002	607
GH-BL32		2000 – 2006	1,486
GH-M3CSL	BMW M3 CSL	2003	150
unknown	BMW M3 Cabriolet	2002	1