## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| CAMPAIGN No.          | Gai-2106   | DATE | Oct. 31, 2014 |  |
|-----------------------|--|------|---------------|--|
| MANUFACTURE           | General Motors Company   |      |               |  |
|                       | (Dealer: YANASE GLOBAL MOTORS)   |      |               |  |
| DESCRIPTION OF DEFECT | General Motors has decided that a defect which relates to motor vehicle safety exists in 2013 and some 2014 model year Cadillac XTS vehicles.  Some of these vehicles have a condition in which the electronic parking brake's   |      |               |  |
|                       | piston actuation arm may not fully retract, which may cause the brake pads to stay partially engaged with the rotor. In this condition, the parking brake indicator may not illuminate even though the parking brake is engaged, which would render a vehicle noncompliant with FMVSS 135.   |      |               |  |
|                       | In addition to the parking brake indicator malfunction described above, the driver may experience poor vehicle acceleration, undesired deceleration, excessive brake heat, and premature wear to some brake components. If the brake drag is significant or if the vehicle is operated for an extended period of time in this condition, there is a potential for the rear brakes to generate significant heat, smoke, |      |               |  |
|                       | and sparks.  |      |               |  |

| TYPE | COMMERCIAL | MODEL YEAR | NUMBER OF |
|------|------------|------------|-----------|
|      | NAME       | RECALLED   | VEHICLE   |
|      | 「XTS」      | 2013-2014  | 42        |
|      |            | TOTAL      | 42        |