

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 4 5 6	DATE	Oct.23.2014
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	For the inflator of the driver's SRS airbag, a wrong part may have been installed to the diaphragm constituting the airbag inflating gas passage and it can, in the event of the airbag deployment, cause abnormal rise in internal pressure of the inflator by which the container of the inflator could be broken and scattered about, causing injury to the vehicle occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-Z12	CUBE	2008~2012	23,908
DBA-NZ12			2,380
DBA-K13	MARCH	2010~2012	73,097
DBA-NK13			5,520
		TOTAL	104,905