

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2099	DATE	Oct. 23. 2014
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that on account of a poor bonded join, the front fairing side panels can come loose at this point when the vehicle is ridden at high speed. This could allow the slipstream to push the fairing side panels out, away from the frame. The side panels are also held by threaded fasteners, however, which would keep them attached to the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BMW S1000R	BMW S1000R	2014	212
		TOTAL	212