

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic  Import Vehicles

CAMPAIGN No.	3453	DATE	21 October 2014
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO. , LTD		
DESCRIPTION OF DEFECT	There is possibility that the engine and brackets fixing bolts will be loosen because of crushing coat of paint of brackets. If it is used continually as this condition, the bolts may drop out. In this case, there is possibility that the engine won't be supported.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-H74	「ZW180-5B」	2013 - 2014	12
UDS-H72	「ZW220-5B」	2013 - 2014	21
WDR-70C6	「70Z7」	2013 - 2014	20
UDS-80C6	「80Z7」	2013 - 2014	28
TOTAL			81