

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3455	DATE	Oct. 16 2014
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On the manually retractable left mirror stay for some heavy-duty touring buses, the mounting bolt on the mirror side stay may loosen and cause cracks at the mirror side stay mount. If the vehicle continues to be used in this condition, the cracks will progress and the left mirror will fall off in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PDG-MM96FH	「FUSO AERO ACE」	2008~2011	9
SDG-MM96FH		2011	1
QDG-MM97FH		2014	1
BKG-MS96JP		2007~2010	384
	「FUSO AERO QUEEN」	2007~2010	11
LKG-MS96VP	「FUSO AERO ACE」	2010~2012	123
QRG-MS96VP		2012~2014	291
		「FUSO AERO QUEEN」	2012~2014
PDG-AM96FH	「SPACEARROW A」	2009	1
BKG-AS96JP		2008~2010	24
		TOTAL	853