

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3446	DATE	October 16, 2014
MANUFACTURER	UNICARRIERS		
DESCRIPTION OF DEFECT	On the trucks with 2 speed type torque converter transmission, it has been found that speedometer cannot be indicated, so it is not satisfied with Japan Safety Standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
XDN-D1F4 XDN-DG1F4	UNICARRIERS FORKLIFT	2014	6
		TOTAL	6