

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2096	DATE	2014/10/10
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	It is possible that the lock for the steering coupling has not been closed correctly. If the lock has not been installed correctly, noises as well as restrictions in steerability of the vehicle may occur. In extreme cases, this may lead to a loss of steerability.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-205040C	C180	2015	2,003
RBA-205042	C200		1,166
RBA-205042C			524
		TOTAL	3,693