

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3445	DATE	October 9 ,2014
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some mid-duty trucks are equipped with exhaust pipes of which welded portions are not strong enough. Due to the pressure applied from the inside of the pipes, the welded portions tend to be stressed excessively to the degree that cracks can be generated on the inner surfaces of the pipes. If the trucks are kept in operation under such a condition, the cracks will grow larger and if things go wrong, exhaust gas will leak from the pipes.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FRR90S1 SKG-FRR90S2 SKG-FRR90T2 TKG-FRR90S1 TKG-FRR90S2 TKG-FRR90T2	[FORWARD]	2010-2013	26,575
SKG-FSR90S2 SKG-FSR90T2 SPG-FSR90S2 SPG-FSR90T2		2010-2013	1,861
LKG-FTR90S2 LKG-FTR90T2		2010-2013	2,499
SDG-GSR90S2		2011-2013	35
		TOTAL	30,970