

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3443	DATE	Oct 8, 2014
MANUFACTURER	Kawasaki Heavy Industries, Ltd.		
DESCRIPTION OF DEFECT	The fuel hose may touch to left side throttle body cover. Therefore the fuel hose may be damaged. In worst case, fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-BJ250A	「ESTRELLA」	2014	1,374
		TOTAL	1,374