

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3440	DATE	Oct. 7 2014
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty hybrid regular-service buses, durability of the inverter in hybrid system is insufficient. If the bus continues to be used in this condition, the inverter may break, and the powertrain drive motor or motor for auxiliaries will become inoperative, causing illumination of the hybrid system warning lamp and lowering of powertrain output. In the worst case, the power steering will become faulty or the bus itself will become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BJG-MP37TK	「FUSO AERO STAR」	2008~2010	3
BJG-MP37TM		2008~2010	33
		TOTAL	36