

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN NO.	3481	DATE	Nov 28th 2014
MANUFACTURER	MITSUBISHI AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>In the piping system of intake air cooling system (intercooler) of engine with turbocharger, fixing force between intercooler hose and intake piping is possibly not enough. As a result, the intercooler hose and intake piping cannot withstand against intake air pressure, and intercooler hose comes off from intake piping. In worst case, amount of black smoke emission may exceed safety standards.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDR-GK13A	「 GCR1350 」	2010 - 2013	47
	「 TA-C1350 」		15
	「 CT1350 」		31
		TOTAL	93