

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3472	DATE	November 28,2014
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	Due to improper location of the screw hole for removing the brake drum in the four wheel drive vehicle, water penetrated into the brake drum through the screw hole may be frozen when the vehicle is parked under the low temperature environment. As a result, the tire may not be able to rotate due to the rear brake lock, and in the worst case scenario, the vehicle may sideslip depending on the condition of the road surface.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-B11W	「eK」	2013~2014	10,629
DBA-B21W	「DAYZ」	2013~2014	16,978
		TOTAL	27,607