

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2116	DATE	Nov 28, 2014
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd.)		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2010-2015 model year Cadillac SRX vehicles. On some of these vehicles, the jam nut in the rear suspension toe adjuster link may not be torqued to the proper specification. A loose toe adjuster link can cause the vehicle to sway or wander at highway speed, activate the vehicle's electronic stability control system, and cause excessive wear to the threads in the link. Additionally, the rear suspension may make loud metallic noises, particularly when the vehicle is travelling over bumps or potholes. If the threads in the link become worn, the link may separate. If separation occurs while the vehicle is being driven, it would create sudden vehicle instability, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-T166C	「SRX」	2010 - 2014	823
		TOTAL	823