

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2110	DATE	November 11 <sup>th</sup> 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The nut for fixing the emergency wheel and carrier to the vehicle is inappropriate. Thus, the nut may gradually loosen due to vehicle vibration and noise may occur. When keep driving under this condition, the nut may completely go off, and in worst case the emergency wheel and carrier can separate from the vehicle underbody.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-XM15	MINI Cooper	2014	14
TOTAL			14