VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3 4 6 8	DATE	Nov 7,2014		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	Due to inadequate strength of the axle (hub) internal gear on wheel cranes' travel device, there is a risk of the gear cracking. Therefore, with continued use of the crane under this condition there is a risk that the gear will be damaged resulting in inability to travel.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-T010	TADANO 「GR-130N-1」	2013-2014	268
WDR-EK05	KOBELCO 「RK130」	2013-2014	23
		TOTAL	291