

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	GAI-2108	DATE	07/11/2014
MANUFACTURE	McLaren (Japanese Importer : McLaren Automotive ASIA Pte Ltd)		
DESCRIPTION OF DEFECT	It has been identified that a number of Right hand drive McLaren vehicles have been fitted with electrical wiring harnesses with an incorrect configuration which affects the operation of the seatbelt pretensioner system within the occupant restraint controller.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MP4-12C	「McLaren MP4-12C」	2012-2013	35
ABA-MP4-12CS	「McLaren MP4-12C Spider」	2013	25
ABA-MP4-12CP	「McLaren 650S Coupe」	2014	4
ABA-MP4-12CSP	「McLaren 650S Spider」	2014	6
		TOTAL	70