

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2112	DATE	2014/11/27
MANUFACTURE	SANYANG INDUSTRY CO., LTD. (Japanese Importer : M'z&COMPANY LTD.)		
DESCRIPTION OF DEFECT	In the license-plate lamp, due to inappropriate material for the resin cover, valve heat arising from long-term use can cause the cover to melt. In the worst case scenario, there is a risk that this could lead to vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LF18W	RV200i	2009 ~ 2011	222
LF12W	RV125i	2009 ~ 2011	1238
		TOTAL	1460