

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ /Import Vehicles

CAMPAIGN No.	Gai-2120	DATE	1/December/2014
MANUFACTURER	Automobiles Volvo Car Corporation (Japanese Importer: Volvo Car Japan Limited)		
DESCRIPTION OF DEFECT	Left rear positioning light may stop functioning which illuminated the Bulb failure light and display a message in the Drivers Information Module. The corrective action is to update the software for the Central Electronic Module.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VOLVO	[V40]	2014	165
	[V40CC]	2014	26
		TOTAL	191