

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	3482	Date	Dec., 3rd, 2014
Manufacture	Caterpillar Japan LTD		
Description of Defect	An electrical wiring on engine may contact fuel system components. When wiring is worn by another parts, electrical system may occur short circuit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-MCC	「938H」	2010 - 2013	130
		TOTAL	130