

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	gai-2111	DATE	Dec. 11, 2014
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	Number plate holder subframe base broken by fatigue stress. This phenomenon is insufficient dynamic strength. Not evidences of mistakes in the manufacturing process. It is caused by mistakes design. All under recall campaign bikes change number plate holder subframe for countermeasures product.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZDMG100ABBB	DIAVEL/DIAVEL CARBON	2011-2012	653
ZDMG100ABCB	DIAVEL/DIAVEL CARBON/DIAVEL CROMO/DIAVEL DARK	2012-2013	410
ZDMG100ABDB	DIAVEL CARBON/DIAVEL DARK	2013	35
ZDMG102JCDB	DIAVEL CARBON/DIAVEL DARK/DIAVEL STRIPE	2013	298
ZDMG102JACB	DIAVEL AMG	2013	130
ZDMG102JBDB	DIAVEL STRADA	2013-2014	129
		TOTAL	1655