## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2127	DATE	December. 11. 2014	
MANUFACTURER	HONDA OF AMERICA MFG., INC.			
DESCRIPTION OF DEFECT	With regard to the passenger's airbag inflator, an inflator container broke into fragments when a non-Honda make of vehicle was dismantled. Although the cause is not determined yet, in view of the present situation where inflators of the same model year and type as the said inflator have the possibility that their containers might break into fragments and scatter about in the event of the airbag deployment, incurring the risk of catching fire or causing injury to vehicle occupants, subject airbags in all vehicles will be replaced with non-defective inflators by way of precautionary measures.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
UA-YH2	「ELEMENT」	2003~2004	1,741
		TOTAL	1,741