

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|--|------|-------------------|
| CAMPAIGN No. | 3484 | DATE | December 11, 2014 |
| MANUFACTURER | UD Trucks Corporation | | |
| DESCRIPTION OF DEFECT | <p>Due to inappropriate heat-treatment of the propeller shaft between the rear front axle and the rear rear axle, some relevant sleeves are lacking in strength. If the vehicle is operated without fixing the problem, cracks in the sleeves may occur. In severe cases, the propeller shaft may be broken, rendering the vehicle inoperable.</p> | | |

| TYPE | COMMERCIAL NAME | MANUFACTURED YEAR OF RECALLED VEHICLES | NUMBER OF VEHICLES |
|---|------------------|--|--------------------|
| QKG-CG5YA | UD Trucks Quon | 2014 | 1 |
| QKG-CG5YE | UD Trucks Quon | 2014 | 1 |
| QDG-CG5ZA QKG-CG5ZA QKG-CG5ZA KAI | UD Trucks Quon | 2014 | 198 |
| QKG-CG5ZE | UD Trucks Quon | 2014 | 15 |
| QKG-CG5ZL | UD Trucks Quon | 2014 | 12 |
| QKG-CG5ZM | UD Trucks Quon | 2014 | 4 |
| QKG-CW5XL | UD Trucks Quon | 2014 | 278 |
| QKG-CW5YL QKG-CW5YL KAI | UD Trucks Quon | 2014 | 41 |
| QKG-CW5ZA | UD Trucks Quon | 2014 | 5 |
| QKG-CW5ZL | UD Trucks Quon | 2014 | 30 |
| QDG-CX5YA QKG-CX5YA | UD Trucks Quon | 2014 | 5 |
| QKG-CX5YL | UD Trucks Quon | 2014 | 1 |
| QDG-CZ5YL QDG-CZ5YL KAI | UD Trucks Quon | 2014 | 90 |
| QDG-PW39L QDG-PW39L KAI | UD Trucks Condor | 2014 | 30 |
| QDG-SZ5YL | Isuzu - | 2014 | 1 |
| QDG-HZ5YL | Hino - | 2014 | 1 |
| | TOTAL | | 713 |