

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 4 9 2	DATE	Dec.11.2014
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On an inflator of front passenger air bag, the inflator container was ruptured when the air bag was deployed intentionally at vehicle demolition work for the other automotive manufacture. Therefore, the cause does not become clear, but changes the inflator with a new one as preventive measures because the inflator container as for the same type of inflator with the same year type may be ruptured and the metal fragments may be scattered, which can lead to smolder or lead to be got injured the passenger when the air bag is deployed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-TU31	PRESAGE	2003	15,068
UA-TNU31			3,914
UA-PU31			794
UA-PNU31			525
TA-NT30 UA-NT30	X-TRAIL		13,754
TA-T30 UA-T30			1,508
GH-PNT30			462
UA-J31			11,907
UA-PJ31	TEANA		1,013
UA-TNJ31			950
UA-QG10			11,500
TA-QNG10	BLUEBIRD SYLPHY		1,177
UA-FG10			4,580
GH-TG10			1,389

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
UA-RM12	LIBERTY	2003	8,478
UA-RNM12			1,248
TA-QE25	CARAVAN		828
TA-QGE25			1,499
GE-CQGE25 LC-CQGE25			327
KG-CWGE25			102
KG-CWMGE25			174
GE-VPE25 LC-VPE25			343
KG-VWE25			210
KG-VWME25			321
GE-DQGE25 LC-DQGE25			250
KG-DWGE25			302
KG-DWMGE25			131
TA-WFGY61			SAFARI
TA-JQE25	ISUZU COMO	7	
TA-JQGE25		33	
LC-JCQGE25		8	
KG-JCWGE25		2	
KG-JCWMGE25		2	
GE-JVPE25 LC-JVPE25		2	
KG-JVWE25		9	
KG-JVWME25		5	
GE-JDQGE25 LC-JDQGE25		2	
KG-JDWGE25		2	
KG-JDWMGE25		1	
		TOTAL	82,951