

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2129	DATE	December 19 th , 2014
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The front seats' backrest angle adjustment production procedure was faulty. Thus, the spline teeth cannot fully interlock, which may lead to insufficient fixation of reclining position. As a result, in case of a high impact, the front seat backrest may recline backwards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-XM12	MINI One	2014	3
DBA-XM15	MINI Cooper	2014	81
DBA-XM20	MINI Cooper S	2014	263
		TOTAL	347