

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2136	DATE	Jan 7, 2015
MANUFACTURE	Harley Davidson Motor Company (Japanese Importer : Harley Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	On certain model year 2014 and 2015 SOFTAIL SLIM model motorcycles the operation of the turn signals will not include lamp-outage detection for the front turn signals due to an incorrectly programmed setting within the Body Control Module (BCM) that is set by Harley-Davidson.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JR5	SOFTAIL SLIM	2014 (MY)	283
EBL-FS5	SOFTAIL SLIM	2015 (MY)	108
		TOTAL	391