

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2134	DATE	9 Jan 2015
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Motorcycles Japan K.K.)		
DESCRIPTION OF DEFECT	It has been identified that the side stand pivot bolt has been manufactured with insufficient material cross section to withstand abusive loads on the Explorer and Explorer XC models. This could result in the bolt fracturing and the machine falling over.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
VG	TIGER EXPLORER	2012-2014	171
	TIGER EXPLORER XC	2013-2014	62
		TOTAL	233