

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	GAI-2140	DATE	January 14, 2015
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	<p>The fuel delivery hoses located in the engine bay could have been damaged during the assembly process at the supplier in the joint between the polyamide hose and the plastic.</p> <p>This could lead to a fuel leakage that causes fuel smell in cabin.</p> <p>No fire events were detected in the vehicles found defective in plant.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MG30AA	「Ghibli S Q4」	2015	1
ABA-MG30A	「Ghibli S」	2015	1
ABA-MG30B	「Ghibli」	2015	1
		TOTAL	3