

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	3508	DATE	January 29 ,2015
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	<p>On light-duty trucks, due to the lack of strength of the welds fixing the baffle plates to the fuel tank, the baffle plates would fluctuate with the fuel sloshing inside the tank, leading the spot welded locations to be cracked; (baffle plates are partitioning plates located inside of the fuel tank designed to prevent excessive fuel sloshing). If the vehicle continues to be used in this condition, it may cause cracks to be extended to the fuel tank, and in the worst case, it may permit fuel leakages.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-NJR85AN BKG-NJR85N SKG-NJR85AN SKG-NJR85N TKG-NJR85A TKG-NJR85AN TKG-NJR85N	[ELF]	2009-2013	82
BDG-NKR85N BDG-NKR85R BKG-NKR85AN BKG-NKR85AR BKG-NKR85N BKG-NKR85R SKG-NKR85AN SKG-NKR85AR SKG-NKR85N SKG-NKR85R TKG-NKR85AN TKG-NKR85AR TKG-NKR85N TKG-NKR85R	[ELF]	2009-2013	2,378
PDG-NKR85YN SKG-NKR85YN	[ELF]	2009-2013	1,122
BDG-NLR85AN BJG-NLR85AN BKG-NLR85AN BKG-NLR85AR BKG-NLR85N SJG-NLR85AN SKG-NLR85AN SKG-NLR85AR SKG-NLR85N TKG-NLR85AN TKG-NLR85AR TKG-NLR85N TOG-NLR85AN	[ELF]	2009-2013	3,403

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-NLS85AN BKG-NLS85AR SKG-NLS85AN SKG-NLS85AR TKG-NLS85AN TKG-NLS85AR	[ELF]	2009-2013	321
BDG-NMR85AN BJG-NMR85AN BKG-NMR85AN BKG-NMR85AR BKG-NMR85N BKG-NMR85R SDG-NMR85AN SJG-NMR85AN SKG-NMR85AN SKG-NMR85AR SKG-NMR85N SKG-NMR85R SQG-NMR85AN TDG-NMR85AN TKG-NMR85AN TKG-NMR85AR TKG-NMR85N TKG-NMR85R TOG-NMR85AN		2009-2013	7,630
BDG-NMS85AN BDG-NMS85AR SDG-NMS85AN SDG-NMS85AR SKG-NMS85AN SKG-NMS85AR TDG-NMS85AN TDG-NMS85AR		2009-2013	593
TKG-AJR85AN	[ATLAS]	2012	2
BDG-AKR85N BDG-AKR85R BKG-AKR85AN BKG-AKR85AR BKG-AKR85N BKG-AKR85R SKG-AKR85AR SKG-AKR85R TKG-AKR85AN TKG-AKR85AR TKG-AKR85N TKG-AKR85R		2009-2012	79
PDG-AKR85YN SKG-AKR85YN		2010-2012	4
BKG-ALR85AN BKG-ALR85AR SKG-ALR85AN SKG-ALR85AR TKG-ALR85AN TKG-ALR85AR TKG-ALR85N		2009-2012	141

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-ALS85AN BKG-ALS85AR SKG-ALS85AN SKG-ALS85AR TKG-ALS85AR	[ATLAS]	2009-2012	38
BJG-AMR85AN BKG-AMR85AN BKG-AMR85AR BKG-AMR85N BKG-AMR85R SJG-AMR85AN SKG-AMR85AN SKG-AMR85AR SKG-AMR85N SKG-AMR85R TKG-AMR85AN TKG-AMR85AR TKG-AMR85N TKG-AMR85R		2009-2012	339
BDG-AMS85AN SDG-AMS85AN TDG-AMS85AN		2009-2012	10
BKG-BJR85AN	[CONDOR]	2009-2011	2
BKG-BKR85AR BKG-BKR85R		2010	5
PDG-BKR85YN		2009-2010	5
BKG-BLR85AN BKG-BLR85AR		2009-2011	13
BKG-BLS85AR		2010-2011	2
BKG-BMR85AN BKG-BMR85AR BKG-BMR85N BKG-BMR85R		2009-2011	70
BDG-BMS85AN		2010	1
TKG-BJR85AN		2012	1
SKG-BKR85N TKG-BKR85N TKG-BKR85R		2012-2013	3
SKG-BKR85YN		2012	2
TKG-BLR85AN TKG-BLR85AR		2012-2013	28
TKG-BLS85AR		2012-2013	4
SKG-BMR85AN SKG-BMR85AR SKG-BMR85N SKG-BMR85R TKG-BMR85AN TKG-BMR85AR TKG-BMR85N TKG-BMR85R		2011-2013	50
TDG-BMS85AN TDG-BMS85AR		2012-2013	4

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
SKG-LJR85N TKG-LJR85N	[TITAN]	2012	3	
BDG-LKR85N BKG-LKR85AN BKG-LKR85AR BKG-LKR85N BKG-LKR85R SKG-LKR85AR SKG-LKR85N SKG-LKR85R TKG-LKR85AN TKG-LKR85AR TKG-LKR85N TKG-LKR85R		2009-2013	91	
PDG-LKR85YN SKG-LKR85YN		2010-2013	7	
BKG-LLR85AN BKG-LLR85AR SKG-LLR85AN SKG-LLR85AR TKG-LLR85AN TKG-LLR85AR		2009-2013	184	
BKG-LLS85AR SKG-LLS85AR TKG-LLS85AR		2009-2013	27	
BKG-LMR85AN BKG-LMR85AR BKG-LMR85N BKG-LMR85R SKG-LMR85AN SKG-LMR85AR SKG-LMR85N SKG-LMR85R TKG-LMR85AN TKG-LMR85AR TKG-LMR85N TKG-LMR85R		2009-2013	331	
BDG-LMS85AN SDG-LMS85AN SDG-LMS85AR TDG-LMS85AN		2010-2013	8	
		TOTAL	16,983	

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
BKG-NHR85A TKG-NHR85AN	[ELF]	2011-2012	2	
BKG-NJR85A BKG-NJR85AN SKG-NJR85A TKG-NJR85A		2007-2012	7	
TKG-NJS85A		2012-2013	2	
BDG-NKR85AN BDG-NKR85N BDG-NKR85R BKG-NKR85A BKG-NKR85AN BKG-NKR85AR SKG-NKR85A TKG-NKR85A		2007-2013	19	
PDG-NKR85YN		2007-2009	13	
BKG-NLR85AN BKG-NLR85AR BKG-NLR85N SKG-NLR85AN		2006-2011	45	
BKG-NLS85AN BKG-NLS85AR		2007-2009	3	
BDG-NMR85AN BDG-NMR85AR BDG-NMR85N BDG-NMR85R BJG-NMR85AN BKG-NMR85AN BKG-NMR85AR BKG-NMR85N SKG-NMR85AN		2006-2011	58	
BDG-NMS85AN		2007-2008	4	
BDG-AMR85AN		[ATLAS]	2009	1
BKG-LLR85AN BKG-LLR85N		[CONDOR]	2007	2
		TOTAL	156	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
Fuel Tank	8-98021295-3	2009-2010	14
	8-98021295-4	2010-2014	118
	8-98118058-1	2011-2013	24
		TOTAL	156