

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3514	DATE	Jan. 29 2015
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On a carbon-monoxide emission prevention system for heavy-duty regular-service bus, the control program for the engine control unit and the exhaust gas after-treatment control unit is improper. This causes insufficient injection of urea, and the NOx contents in the exhaust gas may exceed standard.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-MP35FM	「FUSO AERO STAR」	2014～2014	7
QDG-MP35FP		2013～2014	22
QKG-MP35FK		2013～2014	15
QKG-MP35FM		2013～2014	117
QKG-MP35FP		2013～2014	91
QKG-MP37FK		2013～2014	217
QKG-MP37FM		2013～2014	89
QKG-MP38FK		2014～2014	100
QKG-MP38FM		2014～2014	32
		TOTAL	690