

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2142	DATE	January 30 <sup>th</sup> , 2142
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The component part of the retractor on the front right seat belt might be inappropriately manufactured, so that the retractor might be locked at low outside temperature. In such case, the passenger can not pull out and fasten the seat belt.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-2A15	BMW 218i Active Tourer	2014	280
DBA-4B30	BMW 435i Gran Coupe	2014	2
		TOTAL	282