

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2138	DATE	Feb 20, 2015
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K.)		
DESCRIPTION OF DEFECT	On certain model year 2012 Dyna Model and Softail Model motorcycles, the front brake master cylinders may experience corrosion in the threads for the brake line banjo bolt. A corrosive condition at the banjo bolt threaded joint may lead to a leak causing a loss of front brake performance. If this condition remains undetected it could result in a sudden loss of brake fluid, which could lead to a loss of front brake function, possibly resulting in a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BW5	HERITAGE SOFTAIL CLASSIC	2012	235
BX5	FAT BOY	2012	165
GN4	LOW RIDER	2012	164
GP4	WIDE GLIDE	2012	67
GV4	SUPER GRIDE CUSTOM	2012	22
GX4	STREET BOB	2012	92
GZ4	SWITCHBACK	2012	195
JD5	SOFTAIL DELUXE	2012	106
JN5	FAT BOY LO	2012	126
JP5	BLACK LINE	2012	68
JR5	SOFTAIL SLIM	2012	203
GY4	FAT BOB	2012	17
		TOTAL	1460