

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import Vehicles~~

CAMPAIGN No.	Gai-2151	DATE	2015/02/18
MANUFACTURE	MASSEY FERGUSON SA (Japanese Importer :MSK Farm Machinery Corporation CEO Toshiki Sugino)		
DESCRIPTION OF DEFECT	The high pressure fuel pipe between the HP fuel pump and the common rail, located on the left hand side of the engine, may crack to leak fuel due to vibration from the engine. In the worst case, the engine may become unable to start. The HP fuel pipe should be replaced with a new pipe to retain with an anti-vibration bracket.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDR-SU49A	MF6612-4	2014	15
	MF6613-4	2014	26
	MF6614-4	2014	4
	MF6615-4	2014	1
WDR-SU49A2	MF6614-4CVT	2014	1
		TOTAL	47