

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2150	DATE	February 13 <sup>th</sup> , 2015
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	There is a possibility that the wiring harness and the connector pin at the fuel delivery unit was inappropriately crimped. Thus, it might lead electrical resistance increase and overheating of the respective area. Then finally fuel leakage can happen.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-5M1C	B5 Biturbo	2010 – 2011	33
ABA-5M1A	B5 Biturbo Touring	2011	1
		TOTAL	34