

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2139	DATE	Feb 12 <sup>th</sup> 2015
MANUFACTURE	PIAGGIO & C.s.p.a (Japanese Importer : PIAGGIO Group Japan Corporation )		
DESCRIPTION OF DEFECT	In a fuel pump, the clearance of the impeller and fuel pump cover was inappropriate. Therefore, by a rise in fuel temperature, the impeller expands and interfere it with the cover when a rider stops an engine after a vehicle warm-up in the summer when outside temperature is high. And the impeller does not turn appropriately and cannot supply fuel and may not restart an engine.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZD4RB ZD4VR ZD4VBB ZD4VBH ZD4VS ZD4VP	「SCARABEO 125 i.e.」 「SCARABEO 250 i.e.」 「SPORTCITY 250 i.e.」 「SPORTCITY CUBE 250 i.e.」 「SXV550」 「RXV450」	2008~2010	SCARABEO125 i.e. 64 units SCARABEO250 i.e. 42 units SPORTCITY 250 i.e. 21 units SPORTCITY CUBE 250 i.e. 132 units SXV550 6 units RXV450 1 unit
		TOTAL	266 units