

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2141	DATE	Feb. 6, 2015
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	SAFETY RECALL: Certain 2014 Model Year EcoSport Vehicles - EcoSport Fuel Vapour Tube Replacement Certain vehicles have been fitted with a Fuel Vapour Tube which does not have adequate corrosion-resistant protective coating. It is possible that the Fuel Vapour Tube may corrode.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA - MAJUEJ	EcoSport	2014	69 unit
		TOTAL	69 units