

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3537	DATE	31 Mar 2015
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>Some parking brake buttons have little sliding space inside due to insufficient production processing. If the outside air temperature becomes low, the brake button shrinks and the resistance of the sliding portion increases, and in the worst case, the parking brake cannot be cancelled.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-CP220	「CP220-3」	2013	80
KDP-N22A2	「HN220WHH-2」	2013	6
—	「ZC35C-3」	2013	102
—	「HW30VWH-5」	2013	10
—	「ZC35T-3」	2013	4
—	「ZC50C-3」	2013	115
—	「HW41VWH-5」	2013	8
—	「ZC50T-3」	2013	5
TOTAL			330