

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2144	DATE	March 31, 2015
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a temporary screw connection assembly problem, existing threaded connections on the camshaft controller can become strained to such an extent that the function of the camshaft controller cannot be guaranteed over the service life of the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-970M46	「Panamera」	2011	106
		2012	41
	「Panamera 4」	2011	66
		2012	26
ABA-970M46A	「Panamera」	2011	8
		2012	3
	「Panamera 4」	2011	7
		2012	3
ABA-970M48A	「Panamera S」	2010	221
		2011	62
		2012	22
	「Panamera 4S」	2010	303
		2011	78
		2012	31
	「Panamera Turbo」	2010	143
		2011	65
2012		5	
ABA-970M48TA	「Panamera Turbo S」	2012	6
ABA-92AM48	「Cayenne S」	2011	127
		2012	36

ABA-92AM48A	「Cayenne S」	2011	40
		2012	11
ABA-92AM48A	「Cayenne Turbo」	2011	173
		2012	30
		TOTAL	1613