

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	3 5 3 2	DATE	March 30. 2015
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED Kamiechi Uenohara 3034, Atsugi-city Kanagawa Japan		
DESCRIPTION OF DEFECT	This recall concerns trailer turn signals; owing to an inappropriate choice of turn signals, the anomaly detection system inside the flasher relay does not work in case of a signals' breakdown, because of which the operation condition display disposed in front of the driver's seat does not function.		

TYPE	COMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFPDF241A	—	DFPDF241A-72082 June 26. 2007	1
DFPDG341A		DFPDG341A-20018 September 27. 2007	1
DFPDG341AN		DFPDG341AN-20015~DFPDG341AN-20016 January 22. 2007~March 13. 2007	2
DFPFF241B		DFPFF241B-72327~DFPFF241B-72409 March 3. 2007~August 20. 2007	3
DFPFF241BN		DFPFF241BN-30052 March 1. 2007	1
DFPFH341A		DFPFH341A-20082~DFPFH341A-20232 March 25. 2005~August 1. 2007	14
DFPFH341AN		DFPFH341AN-20010~DFPFH341AN-20019 September 16. 2006~February 20. 2007	4
DFPTF341A		DFPTF341A-20003~DFPTF341A-20030 August 16. 2006~September 12. 2007	5
DFPTF341AN		DFPTF341AN-20020~DFPTF341AN-20053 September 25. 2006~September 27. 2007	7
DFWDF342CN		DFWDF342CN-72028 May 27. 2006	1
DFWFF241AN		DFWFF241AN-30011 May 31. 2007	1
DFWTF241AN		DFWTF241AN-30088 March 21. 2006	1
DFWTF241B		DFWTF241B-73016 December 2. 2006	1
DFWTF241BN		DFWTF241BN-30610~DFWTF241BN-30864 August 26. 2006~September 12. 2007	9
MODEL 14 models	—	PRODUCTION March 21. 2006~September 27. 2007	TOTAL 51 units